

















24X M8X20

24X M8










12X M8X20

12X M8











4X U-BYGEL M10





8X M10















$$A=B \pm 10\text{mm}$$













12X M8X20


12X M8






























4X M8X20




4X M8















64X M8X20



64X M8







Alternativ
Farmarskruv 20X



Popnit 20X

